





7 TIPS FOR MATERIALS TESTING





Introduction



Static materials test system
(electromechanical drive)



Static materials test system
(hydraulically powered)

Characterizing material properties is a primary objective for quality control and R&D laboratories. Yet, choosing the right test is not always obvious. There are many different types of static and dynamic tests, including: tensile, compression, shear flexure and fatigue/fracture.

The following should be considered when choosing the correct testing system:

- **Test Type:** tensile, compression, flexure, torsion, shear, reverse-stress (torsion and compression)
- **Testing Specimens:** configuration, size, shape and material
- **Ultimate Test Loads:** the highest expected load expressed in pounds, newtons or kilograms
- **Ultimate Strain-Extension/Compression:** the highest expected elongation expressed as a percentage of initial gauge length
- **Strain Measurements:** extensometer gauge length, percentage of travel, other requirements

This pamphlet aims to offer tips on how to choose the right testing machine based on these and other considerations.

Table of Contents

| | |
|---|-------|
| Tip 1: Grip Selection | 4-6 |
| Tip 2: Load Cell Selection | 7 |
| Tip 3: Extensometry Selection | 8-9 |
| Tip 4: Optimizing Specimen Alignment | 10-11 |
| Tip 5: Accuracy, Resolution and Precision | 12-13 |
| Tip 6: Data Rate and Bandwidth | 14-15 |
| Tip 7: Software Function and Performance | 16-18 |
| Notes | 19 |
| Contact Details | 20 |



Dynamic test system



Impact test system



Tip 1: Grip Selection



Mechanical wedge action grip



Self-tightening roller grip

Successful gripping solutions require the specimen to be held in a way that prevents slippage and jaw breaks and ensures axiality of the applied force. In some cases the gripping requirements are very specific and a purpose-designed grip or fixture is necessary to meet a particular testing standard. However, in most cases, you can use general purpose accessories. General purpose grips and fixtures have the advantage of being able to grip a wide variety of specimen types and materials using a range of options such as different jaw faces, alignment fixtures, etc.

Specimen Gripping Solutions

Two of the most common problems operators face are specimen slippage and jaw breaks. Slippage occurs most frequently when using mechanical or screw action grips with flat faces. When selecting grip faces, the surface area should be large enough to cover the tab (for dumbbell samples) or, for a parallel sample, as much of the surface area as possible. With any grip, ensure that the specimen end is gripped by at least 75% of the available jaw face length, otherwise gripping efficiency is reduced and in some cases, the jaw face can be damaged.

The important thing to remember if you experience gripping problems is to experiment. How you arrive at the end result is incidental.

Jaw breaks usually occur when the sample inside the grips is damaged by too much clamping force or by serrated faces biting too deep. Below are tips to reduce jaw breaks:

- **Screw Action Grips:** The operator may be using too much force when tightening onto the sample; use a torque wrench or pneumatic grips.
- **Pneumatic Grips:** Drop the pressure, but not to the point where you get slippage.
- **Serrated Faces:** Change to faces that have more serrations per inch (less bite) or cover with masking tape or comparable material (this will soften the bite and prevent damage to the sample).


Testing Monofilaments and Single Fibers

A single fiber, or monofilament, may be affixed to an aperture card. The gauge length of the specimen is the height of the aperture. The card is cut on the slant on either side of the specimen after it has been mounted in the test instrument.




Hints for Reliable Gripping


- Periodically inspect the grips for defects such as cracks or leaks in hoses.
- Periodically verify pressure gauges are accurately registering air or oil pressure to the gripping system.
- Replace jaw faces when the surfaces become worn, damaged or contaminated.
- Do not use more gripping force than necessary to provide reliable, slip-free gripping.
- Old grips don't necessarily work with new materials or specimens.
 - ~ You may find that special grips or different jaw face surfaces are needed.
 - ~ You can try a variety of things to modify existing gripping methods including emery cloth, sticky tape, etc.



Tensile test of single fibers



Line contact grip face



Plain ground grip face



Anti-seize lubricant



Tip 2: Load Cell Selection

Characteristics of Load Cell

Load cells measure the force experienced by the specimen and output an electrical signal that is used by the electronics to precisely monitor, report or control the force. In order to choose a proper load cell for your test, the following characteristics of load cells should be considered:

- Capacity
- Accuracy
- Repeatability
- Off-set loading error
- Non-linearity
- Compensated temperature range
- Temperature effect on zero and sensitivity
- Life time (especially for dynamic cells)
- Overload capacity
- Off-axis stiffness


Additionally, consider the availability of **self-identification*** to prevent human errors when setting up for a test. It is important to note that most transducer manufacturers specify linearity of their load cells as a percentage of the full-rated output (% F.R.O.). This can be misleading when using lower ranges (say 1% of capacity). A load cell rated at 0.05% F.R.O. produces a reading error of 5% at 1:100th of Full Scale.

Hints for Testing


- Always clamp specimens in the grip not attached to the load cell first (usually upper grip).
- Warm up a load cell a minimum of 15 minutes.
- Once a specimen is clamped in place, don't change the balance or crosshead position controls.
- Never put a load cell in an oven.
- Use the Load Protect function to protect specimens from damage.
- If testing at less than 2% of capacity, think about changing to a lower capacity load cell.



Dynacell™ for dynamic tests



Tip 3: Extensometry Selection



Clip-on extensometer


Necessity of Extensometry

Any mechanical system subjected to a force will deform, however slightly. This applies equally to material testing systems. The load frame, load cell and grips of your system are not infinitely stiff and will deform slightly as force is applied to the specimen. This deformation is called compliance and can lead to significant errors in test results especially for high capacity test with small travel requirements.

Most material test systems measure crosshead or actuator displacement and this can be used as a measure of specimen deformation. However, the displacement output recorded by the system is actually the sum of the system compliance and the specimen deformation.

In many applications, such as tensile testing of plastics and elastomers, the system compliance is often very small when compared to the specimen deformation and the error can be ignored.

Where very precise measurements of specimen deformation are required, the use of extensometers avoids system compliance errors completely.



Long travel extensometer

Extensometer Types

There are two main types of extensometers:

- **Contact Extensometers:** clip-on, long travel, high-temperature, etc.
- **Non-Contact Extensometers:** laser, video

While providing accurate measurement in many applications, contacting extensometers can have an adverse effect on test results. Non-contacting extensometry offers many benefits over traditional contacting devices, including:


- No influence on the test specimen
- No problems with knife-edge slip
- No errors due to inertia of moving parts
- No moving parts eliminate errors due to wear
- No possibility of damage due to energy release at failure
- Can be used with environmental chambers over a wider temperature range



Advanced Video Extensometer (AVE)



Tip 4: Optimizing Specimen Alignment



S-Type and C-Type Bending

Why is Good Alignment Necessary?

The easiest way to put unwanted stresses into a test piece is to bend it. The easiest way to bend it is to misalign it initially and/or load it non-uniformly by:

- **S-Type Bending:** concentricity offset application
- **C-Type Bending:** angular offset application

Many standards (such as ASTM, ISO, etc.) specify quality of testing in terms of % bending, e.g. < 5% of nominal strain or of strain amplitude.

Optimizing Specimen Alignment

As a general rule, ensure that the axis of force application runs through the centerline of the specimen. Off-axis loading of the specimen can lead to various problems:

- Specimen bending, which results in poor modulus values when using single-sided extensometers.
- Specimen buckling in compression and through-zero tests.
- Offset loading of the load cell, leading to errors in output or in extreme cases load cell damage.
- Non-uniform stress conditions within the material, making it behave differently.

- Edge effects caused by high local stress at the specimen edges.
- Scattered test results if the misalignment is random.

There are several ways to improve the alignment of the specimen. Some applications require the use of additional fixturing to obtain the best possible alignment, where others may simply require more attention by the operator to ensure the specimen is loaded accurately and consistently.

Flexible or universal couplings can be employed to allow the grip to align itself with a slightly bent specimen. Some types of grips employ two universal couplings, one at the top and one at the bottom.

A variety of grips and fixtures feature specimen stops that allow the specimen to be accurately and repeatedly located.




Spherically-seated compression platen for rock test



Specimen centering device



Tip 5: Accuracy, Resolution and Precision



Accuracy



90° constant angle peel fixture

In order to identify a required test and define the requirements for testing machines, it is important to understand the difference between accuracy, precision and resolution.


Accuracy

Accuracy describes how close a measurement is to the actual value. It is important to note how the accuracy of a device or instrument is stated. It is usually presented in one of two forms - percent of full scale or percent of reading. Percent of full scale is often shown as %FS. This is a fixed error and the error as a percent of reading becomes much greater at lower forces. For example, device X has a 200 lbf capacity and an accuracy of 0.3%FS (typical of force gauges). This means that at 20 lbf, the error will be 0.3%FS, or 0.6 lbf, which is 3% of the reading (this is outside of the ASTM requirement that measurements to E 4 be within 1% of reading).

Percent of reading is often shown as %RO (percent of readout). Instruments that specify accuracy as a %RO typically have a wider range of use, since this is a more difficult specification to meet. For example, device X has a 200 lbf capacity and an accuracy of 1% RO (more typical of testing machines). This means that at 20 lbf the error will be 1% of the reading, or 0.2 lbf (within ASTM E 4 requirements).

Precision


Precision (or repeatability) means that you can hit the same point time and again within certain error limits. But, as the target illustrates, you can be precise without being accurate. Precision alone does not ensure accuracy; accuracy is best achieved with both precision and calibration. This means that you not only repeat time and again within prescribed error limits, but also that you hit what you are aiming for.





Precision

Resolution

Resolution describes the smallest increment of measure that a device can discern. For example, a 200 lbf device with a 0.01% resolution can make measurements in increments no smaller than 0.2 lbf.





Tip 6: Data Rate and Bandwidth



Tension test of spring



Ultimate strength of tubing material

Faster is not always better and here's why: The data acquisition rate of a computer or data acquisition system is the rate at which raw data samples are taken. This rate needs to be selected based on the speed at which the incoming signal is changing. If the incoming signal is not changing quickly, then higher data rates only produce excessive data, large files and wasted disk space.

There are three main variables to consider in the data rate discussion:

- The actual signal being measured
- The bandwidth of the signal conditioner (filtering)
- The data acquisition rate

Actual Signal

One of the most critical aspects of proper measurement is to understand the rate at which things occur during a test. For example, when testing composites, there are short, sharp peaks (or signals); but tensile tests on plastics typically show no high frequency signals.

Bandwidth

In order to properly catch these actual events, one needs signal conditioning with the right frequency bandwidth. Bandwidth can be loosely defined as the frequency above which signal changes are not measured - they are

filtered out and flattened. For example, it is not possible to measure 100 Hz peaks with a 10 Hz signal conditioner; the peaks will be smoothed out and become invisible. Most electromechanical testing machines have fixed, low bandwidth signal conditioners, generally on the order of 3 Hz to 5 Hz.

Data Acquisition Rate

The ideal data acquisition rate is a function of the signal conditioning bandwidth, which in turn should be matched to the rate of change of the actual event. A rule of thumb is that a data rate more than 10 times the Signal Conditioning Unit (SCU) bandwidth produces little more than wasted disk space, because the same data is being sampled over and over.

For a complete review of data rate, signal conditioning, noise filtering and how it affects mechanical testing results, consult ASTM Standard Guide E 1942.

Performing tests with appropriate data rate and bandwidth is critical in obtaining accurate and meaningful data.


Hints for Data Collection

On Data Rate

(often defined by the user):
too high = unnecessary amounts of data points
too low = missed peaks and potentially misleading results

On Bandwidth


(often fixed in machine):
too high = noisy signal and loss of resolution
too low = filtered peaks and potentially misleading results




Ultimate strength of tubing material



Tip 7: Software Function and Performance



Runtime screen for prompted test




User-programmed test sequence

Software plays an important role in controlling the testing machine, acquiring and analyzing data and reporting results. A user-friendly interface, easy setup and powerful functions contribute to increased testing productivity. In order to ensure that the function and performance of testing software will meet your requirements, check the following points:

Basic


- **Installation:** This is configured for easy installation and removal by the user.
- **Interface:** It's designed to be intuitive, as well as easy to use.
- **Copy and Paste Capability:** These help you copy result tables and graphs from the software and paste into third-party software packages like MS Word, Excel or PowerPoint.



J-Integral fracture toughness

Test Preparation, Control, Operation

- **Automatic Identification, Calibration, Balancing for Transducer:** These will support preparation of testing and greatly reduce the chance of operator error, calibration errors or bad data, etc.
- **Input Channel:** Many test systems are limited to two channels (load and extension). Additional channels, or optional channels, are important for future capability such as the addition of strain.
- **Test Sequence:** Configured and defined test sequence ensures that operators do the same tests and reduces operating errors.
- **Test Method Creation:** Customizable method templates for standards, such as ASTM, ISO, DIN, JIS, EN, etc. are available.
- **Parameter Settings:** Easy to save and recall test parameters, including specimen data.
- **Raw Data:** Availability to view raw data during the test will help operators detect errors in attaching specimens, extensometers, etc.
- **Compliance Correction:** Compliance correction is available in case the use of extensometers is inconvenient (see Tip-3). Compliance correction is critical for testing strong/stiff materials without extensometry.



Prompted test sequence




Specimen data saved as test parameters





Tip 7: Software Function and Performance


Notes



Reporting options allow users to share detailed test results with ease.

Analysis, Results and Reports

- **Graph:** Appropriate graphs and tables with user definable graphics, labels and auto scaling.
 - **Analysis:** Required calculations (ie: breaking stress, offset yield) and the ability to edit and create user-defined calculations are available.
 - **Report Generation:** Reports are generated in many formats, such as PDF, MS Word, HTML, etc.
 - **Data Export:** This is compatible with third-party application software, such as MS Word, Excel, etc.



Reference help for peel testing

Security, Safety, Help

- **Security:** Availability of user management and password protection.
 - **Upgrades:** Modular-designed structure enables easy addition of functions.
 - **Online Help:** Availability of operating instructions, testing tips and terminologies, etc.
 - **Safety:** User defined limits and end of test criteria.

For information on Instron® products and services, call your local worldwide sales, service and technical support offices:

USA

North America IMT Sales and Service Center

| | |
|-------------------------------|----------------------|
| Sales | Tel: +1 800 564 8378 |
| Service and Technical Support | Tel: +1 800 473 7838 |

North America IST Sales and Service Center

| | |
|-------------------|----------------------|
| Sales and Service | Tel: +1 248 553 4630 |
|-------------------|----------------------|

CANADA

| | |
|---------|---|
| Toronto | Tel: +1 905 333 9123 +1 800 461 9123 |
|---------|---|

**SOUTH AMERICA, CENTRAL AMERICA,
MEXICO AND CARIBBEAN**

Brazil

| | |
|---|-----------------------|
| Sao Paulo | Tel: +55 11 4689 5480 |
| Caribbean, Mexico, South America and Central America | |

Norwood

Tel: +1 781 821 2770

EUROPE

| | |
|--|------------------------|
| United Kingdom, Ireland, Sweden, Norway and Finland | |
| High Wycombe | Tel: +44 1494 456815 |
| Benelux and Denmark | |
| Edgeman | Tel: +32 3 454 0304 |
| France | |
| Paris | Tel: +33 1 39 30 66 30 |
| Switzerland | |
| Zurich | Tel: 0800 561 550 |
| Germany and Austria | |
| Darmstadt | Tel: +49 6151 3917 444 |
| Italy | |
| Milan | Tel: +39 02 390 9101 |
| Spain and Portugal | |
| Barcelona | Tel: +34 93 594 7560 |

ASIA

| | |
|-----------|------------------------|
| China | |
| Beijing | Tel: +86 10 6849 8102 |
| Shanghai | Tel: +86 21 6215 8568 |
| India | |
| Chennai | Tel: +91 44 2 829 3888 |
| Japan | |
| Tokyo | Tel: +81 44 853 8520 |
| Osaka | Tel: +81 6 6380 0306 |
| Nagoya | Tel: +81 52 201 4541 |
| Korea | |
| Seoul | Tel: +82 2 552 2311/5 |
| Singapore | Tel: +65 6774 3188 |
| Taiwan | |
| Hsinchu | Tel: +886 35 722 155/6 |
| Thailand | |
| Bangkok | Tel: +66 2 513 8751 |
| AUSTRALIA | |
| Melbourne | Tel: +61 3 9720 3477 |

Corporate Headquarters

Instron Corporation
825 University Avenue
Norwood, MA 02062-2643 USA
Tel: +1 800 564 8378
+1 781 575 5000
Fax: +1 781 575 5725

European Headquarters

Instron Limited
Coronation Road
High Wycombe, Bucks
HP12 3SY United Kingdom
Tel: +44 1494 464646
Fax: +44 1494 456814

Industrial Products Group

900 Liberty Street
Grove City, PA 16127-9005 USA
Tel: +1 800 726 8378
+1 724 458 9610
Fax: +1 724 458 9614

IST GmbH

Landwehrstrasse 65
Darmstadt, D-64293 Germany
Tel: +49 6151 3917-0
Fax: +49 6151 3917-500



www.instron.com

Instron is a registered trademark of Instron Corporation.

Other names, logos, icons and marks identifying Instron products and services referenced herein are trademarks of Instron Corporation and may not be used without the prior written permission of Instron. Other product and company names listed are trademarks or trade names of their respective companies.

Copyright © 2006 Instron Corporation. All rights reserved.

All of the specifications shown in this brochure are subject to change without notice.

WB1244